## **NVL Laboratories, Inc.**

## **Analysis Report Polychlorinated Biphenyls (PCBs)**

4708 Aurora Ave N, Seattle, WA 98103 p 206.547.0100 | f 206.634.1936 | www.nvllabs.com



Client: Rainier Commons, LLC

Address: 918 S. Horton Street, Suite 101

Seattle, WA 98134

NVL Batch #: 1418211.00

Method No.: EPA 8082

Client Project #: 2012-494

Date Received: 10/13/2014

Matrix: Bulk

Samples Received: 1

Attention: Mr. Doug Lansing Project Location: 3100 Airport Way S. Seattle, WA 98134 Samples Analyzed: 1

Lab Sample ID: Client Sample ID: Sample Description:	14129938 100814DLPCB Silver material on brick		
Sample Weight (g) PCB Type	2.1487 mg/Kg(ppm)		
Aroclor 1016	ND		
Aroclor 1221	ND		
Aroclor 1232	ND		
Aroclor 1242	ND		
Aroclor 1248	ND		
Aroclor 1254	5.6		
Aroclor 1260	1.4		
Total: PCB Concentration	7.0		
Reporting Limit (RL)	0.9		

Remarks:	mg/Kg = Milligrams per kilogram	ND = None Detected (less than RL)
	ppm = Parts per million by weight	<ri =="" below="" instrumen<="" limit="" of="" reporting="" th="" the=""></ri>

Sampled by: Client DRAFT Analyzed by: Shalini Patel Date: 10/14/2014

Preparation and analysis of these samples were conducted in accordance with published test methods. Unless stated otherwise, the condition of all samples was acceptable at time of receipt. Reported sample results are based on dry weight and method QC results are acceptable unless stated otherwise. If samples were not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc.. Responsibility for interpretation of the reported data rests with the client.

## NVL Laboratories, Inc. 4708 Aurora Ave N. Seattle, WA 98103 CHAIN of CUSTODY



	47.0100 Er	_	206.914.4646		SAM	IPLE LOG	141	821	1
ax: 206.634.1936				NVL Batch Numbe					
			on Street,	Suite 1	0.1	Client Job Number			
		attle, WA 9		Juice 1	01	Total Sample			
		1.01.23				Turn Around Tim	a 1-Hr 8-Hrs	_ 2	<u>5</u> 6-10
roject M	Manager Mr.	Douglar	noina			Tam / ti dana Tim	2-Hrs 12-Hrs 4-Hrs 24-Hrs	$\begin{bmatrix} 2\\3\\4 \end{bmatrix}$	6-10
	ocation 310			attle WA	98134		Please call for T		24 Hrs
roject L	ocation 510	-o Alipoit	vvay 0. occ	21110, 0071	70104	Email addres	s lansinghomes@a		271113
	Phone: (206	3) 447-026	33 Fax:	(206) 44	7-0299	Cell (b) (6)	3 Idilonighomoo(aga	301.00111	
	estos Air		OSH 7400)		(NIOSH 740:		TEM (EPA Leve	III) Ot	her
	estos Bulk		A/600/R-93/		PLM (EPA P		(EPA Gravimetry)	TEM BU	_K
	d/Fungus	Mold Air			Rotometer C				
TCLI Cr 6	l Metals	Det. Limit FAA (pp ICP (pp GFAA ( Fiberglas	om)	ilter king water /wipe (Are ance Dust irable Dus	a) Paint	RCRA M Arseni t Chips in % Bariun t Chips in cr Cadmi	c (As) Chromi n (Ba) Lead (F	um (C C C	er Metals All 3 copper (Ci lickel (Ni) inc (Zn)
Condi	ition of Pack	age: 🗌 Go	ood 🗌 Dan	naged (no	spillage)	Severe damage (spi	llage)		
Seq.#	Lab ID	Cli	ient Sample	Number	Comments	s (e.g Sample are, Sa	mple Volume, etc)		A/F
1		10	08/4 DI	PCB	REMOV	IED BY HAN	ID FROM S	IW WI	22
2					BLD4	- 13. SIL	VER MATE	RIAL	
3					on ,	BRICK			
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
13 14									
14		Print Belov	v	Sian Bel	ow /	Compa	any	Date	Time
14 15	Sampled by	Print Below		Sign Bel	OW O		any	Date	Time 15/0
14 15	Sampled by			Sign Bel	Lang			Date 10/8/14 16/13/14	
14 15   8 Relin	quished by	D. LAN		Sign Bel	They			Date 10/8/14/16/13/14	1510
14 15 S Relin	quished by Received by			Sign Bel	Strang			Date 10/8/14/16/13/14	15/0
14 15 Relin	equished by Received by Analyzed by	D. LAN		Sign Bel	ow John John John John John John John John			Date 10/8/14 10/13/14	15/0
14 15 Relin R A Result	quished by Received by	D. LAN		Sign Bel	ow long			Date 10/8/14 10/13/14 10/13/14	15/0